

◎ HOLE IN CHASSIS: Ø3.2

PLASTIC TOLERANCE: $L \le 10 \pm 0.2$ $10 < L \le 30 \pm 0.3$ $30 < L \le 50 \pm 0.5$ 網頁圖示供參考,最終以品固公司正式圖面為主 the plastic tolerance is just for your reference; all the measurements and dimensions are according to the "DATA SHEET" issued by PINGOOD.Ball $a x R (b \land f R \land d)$ BAL $a x = 2 + R / $			◎Halogen Free ◎ROHS 2.0 ◎ROHS 六項 cc <i>DRAW NO. PGAS032</i>	mpliant
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	$L \le 10 \pm 0.2$ $10 < L \le 30 \pm 0.3$ $30 < L \le 50 \pm 0.5$ $50 < L \le 100 \pm 0.7$ $100 < L \le 250 \pm 1.2$ ABOVE 250 ± 1.5 UNIT SCALE	The plastic tolerance is just for your reference; all the measurements and dimensions are according	品固企業股份 品基電子(東莞 蘇州品基電子; 東莞市鑽隆商	有限公司 ()有限公司 科技有限公司 貿有限公司
表單號碼QF135		· · · · · · · · · · · · · · · · · · ·	鉚 釘 MOUNTING BUTTON PART NO:	A 1 SIZE 1 SHEET 1 OF 1