


 $\bigcirc$  HOLE IN CHASSIS:



◎ CHASSIS THICKNESS: 1.0~1.5 mm

