


*◎ HOLE IN CHASSIS:* 



© CHASSIS THICKNESS: 0.6 mm

