

 $\bigcirc$  HOLE IN CHASSIS:  $\emptyset 3.0 \sim \emptyset 3.1$  $\bigcirc$  CHASSIS THICKNESS:  $1.4 \sim 1.6$ 

